

ALIGNMENT PROCEDURE – STEP NO. : 3C CORRECTING TOTAL MISALIGNMENT

AS PER OUR EXAMPLE, THE TOP BOTTOM READINGS ARE :



SHIMING REQUIRED FOR RADIAL & AXIAL MISALIGNMENTS RESPECTIVELY HAVE BEEN CALCULATED ON THE PREVIOUS SLIDES. THE TOTAL SHIMING REQUIRED IS CALCULATED AS FOLLOWS:

AMOUNT OF SHIMS REQUIRED IN

	FRONT LEG	REAR LEG
TO CORRECT RADIAL ALIGNMENT	+ 0.10 mm	+ 0.10 mm
TO CORRECT AXIAL ALIGNMENT	+ 0.60 mm	+ 1.20 mm
TOTAL ALIGNMENT CORRECTION	0.10 + 0.60 = 0.70 mm	0.10 + 1.20 = 1.3 mm

THUS, IN ORDER TO DO TOTAL (RADIAL + AXIAL) ALIGNMENT, PUT SHIMS OF 0.70 mm IN FRONT LEG AND 1.3 mm IN BACK LEG OF MOTOR IN OUR EXAMPLE.

ALIGNMENT PROCEDURE – STEP NO. : 3A CORRECTING RADIAL MISALIGNMENT


RADIAL CORRECTION VALUE IS HALF OF THE TOTAL INDICATOR READING.


FOR EXAMPLE : + 0.20

- □ DIAL IS CLAMPED ON PUMP COUPLING AND POINTER IS ON MOTOR COUPLING.
- ☐ DIAL IS SET TO ZERO AT 12 O'CLOCK POSITION.
- □ DIAL IS READING +0.20 mm AT 6 O'CLOCK POSITION.
- ☐ THIS MEANS THAT MOTOR SHAFT IS DOWN (+ SIGN MEANS DIAL POINTER HAS GOT COMPRESSED.)
- ☐ THUS MOTOR SHAFT WILL HAVE TO BE LIFTED UP BY +0.20/2 = 0.10 mm . THAT IS, SHIMMING OF 0.10 mm IS REQUIRED AT ALL THE FOUR LEGS.

IMPORTANT:

FOR RADIAL MISALIGNMENT CORRECTION, THE VALUE OF SHIMMING REQUIRED WILL BE SAME FOR ALL THE FOUR LEGS, AS WE SAW IN THE ABOVE EXAMPLE.








Straightedge alignment

Dial Indicators










Accuracy Speed Ease of use

Accuracy Speed Ease of use

Accuracy Speed Ease of use


Types of misalignment


Offset




Angular











ALIGNMENT PROCEDURE (TAKING ALIGNMENT READINGS) - STEP NO. : 1



- □ DIAL POINTER SHOULD PREFRABLY BE KEPT ON THE MACINE TO BE MOVED.
- THE SUM TOTAL OF BOTH SIDE READINGS SHOULD BE SAME AS SUM TOTAL OF TOP BOTTOM READINGS. IN ACTUAL PRACTICE, WE CAN ALLOW A DIFFERENCE OF ABOUT 15%. THIS RULE IS CALLED VALIDITY RULE.



THUS DIFFERENCE IS LESS THAN 15 %. HENCE ALIGNMENT READING IS VALID.

IMPORTANT:

ALIGNMENT CORRECTION SHOULD BE ATTEMPTED ONLY WHEN SUM TOTAL OF SIDE READINGS AND TOP BOTTOM READINGS ARE MATCHING WITHIN 15 % AS SHOWN IN THE ABOVE EXAMPLE.